

WARD 4 - MAYOR'S PHOTO REPORT – 4/23/09

Primary Fix It: Unit block of Farragut St NW, north side. Issues: Illegal dumping & overgrowth



ILLEGAL DUMPING – FULL LENGTH OF THE ALLEY







EXAMPLE ABOVE OF DUMPED MATERIALS SPREAD ALONG LENGTH OF ALLEY

PACKER TRUCK STARTING THE LENGTH OF THE ALLEY BELOW







BOXES & BOXES OF USED INK CARTRIDGES & OTHER ILLEGALLY DUMPED PRINTER MATERIAL








AFTER THE PACKER-TRUCK CREW CAME THE WEED-WHACKERS & GRAFFITI TEAMS










BEFORE & AFTER – AFTER STILL WET...REAR FENCE OF ROCK CREEK CEMETERY IN FARRAGUT ALLEY



GRAFFITI ABATEMENT TEAM: WILBERT JOYNER & LORI PAYNE – SIGNING IN





VARIOUS DPW TRUCKS PARKED ON NORTH CAPITOL & IN USE (BELOW)





DPW'S DEON RAY – MASTER OF THE CHAIN SAW

POT HOLE FIX-IT: ALLEY – EAST SIDE – 5600 BLOCK OF BROAD BRANCH ROAD NW

Requested by nearby resident.



MONDAY – SURVEY WITH DDOT's MARK BJORGE -

HOLES BEING FILLED ON WEDNESDAY AND THURSDAY...







SEVERAL LARGE, ROUND POTHoles – FILLED IN OVER WEDNESDAY & THURSDAY





DURING – WEDNESDAY MORNING - FROM NORTHAMPTON ST END OF ALLEY





Monday - MCKINLEY STREET END OF ALLEY – LATER, CREW MAKING THEIR WAY DOWN FOR SECOND PASS





McKINLEY STREET END OF ALLEY – CLOSE-UP & REVERSE SHOT BELOW – PATCHED





TODAY – ALLEY PARALLEL TO BROAD BRANCH – OBAMA’S OMB DIRECTOR LIVES HERE, TOO.



ABANDONED VEHICLE REMOVED FROM REAR OF 3820 7TH STREET NW



MISSING ENGINE, SITTING ON CEMENT BLOCKS - DPW FOUND HOMELESS MAN SLEEPING INSIDE



ADDITIONAL CLEAN UP – TO

SIGN REPAIR - ANOTHER STOP SIGN TAGGED ON OREGON AVENUE – THIS AT WESTERN AVE



(Pouring out during each visit...)





DDOT ISSUES: MEETING WITH RESIDENT OF HAMILTON STREET ABOUT SIDEWALK ISSUE



TREES WITH ROOTS THAT HAVE LIFTED SOME SIDEWALK SECTIONS

RESIDENTS COMPLAINED ABOUT VEHICLES ILLEGALLY PARKING NEXT TO HOME (BELOW)

PROBLEM RESOLVED BY MOCRS & THE DPW



WANT TO TURN UN-IMPROVED "ALLEY" INTO ATTRACTIVE GARDEN. MOCRS IS WORKING WITH DDOT ON THIS...



**LOOKING FROM ALLEY BACK TO 7TH STREET NEXT TO
MARCUS CARPENTER FAMILY HOME ON LEFT**

ON-GOING WORK WHICH AREA RESIDENTS REQUESTED: DDOT ARROWS INSTALLED LAST WEEK ON NORTH & SOUTH SIDES OF GRANT CIRCLE FACING NEW HAMPSHIRE AVENUE. THANKS FOR ASSISTANCE FROM THE NATIONAL PARK SERVICE.



ILLEGAL DUMPING ATTACKS



RIGGS ROAD NE BY RAILROAD UNDERPASS – RESPONDING TO RESIDENT’S REQUEST FOR CLEAN-UP





CONSTANT SITE OF DUMPING: CRITTENDEN BELOW NEW HAMPSHIRE



NEW HAMPSHIRE AT DEACTUR – REGULAR ILLEGAL DUMPING SPOT



Sent from BlackBerry to DPW & picked up that day





REAR OF 3819 NEW HAMPSHIRE AVENUE NW - AND BELOW FOLLOWING CLEANING

